Transport



PDBB Powder Big-Bag unloading system

"Simple easy to use big-bag unloading system for PFR60 equipment"



To make filling the PFR60 easier, you can use the PDBB big-bag unloading system, this system can fill your powder feeder based on weight. The powder feeder can be placed on the scale, the auger will transport / fill the coating from the big-bag into the powder feeder. It will automatically stop when the right amount of coating is reached.

There can be placed 2 big-bags on each unit. The big-bags need to be placed in a frame, for a good unloading of this system. Optionally we can provide "powder containers" to have the possibility to switch not empty big-bags. If you are interested in this system, please let us know.



Technical Specifications:

Power supply : 400Vac Single Phase 50Hz / 1 kW

The control panel is equipped with:

- Weight computer for the right amount of product
- Fast/Slow filling for accurate dosing
- Start/Stop and choice switch for left/right big-bag
- Emergency stop for emergency situations

